


XTR Rapidfire Lever

SL-M980-A

Rapidfire Lever

SM-SL98-B

I-spec Bracket (B-type)



ITEM NO.	SHIMANO CODE NO.	DESCRIPTION	INTERCHANGEABILITY	
1	Y6T798070	R.H. Shifting Lever Unit	A	
	Y6T898030	L.H. Shifting Lever Unit	A	
2	Y6T798020	Shifting Lever Fixing Screw Unit	A	
3	Y6CD33000	Inner Hole Cap	A	
4	Y6T798030	Unit Fixing Bolt (M5 x 9.5) & Washer		
	Y6T798050	Unit Fixing Bolt (M5 x 9.5) & Washer for SM-SL98-B	A	
5	Y6T798040	R.H. Cable Adjusting Bolt Unit	A	
	Y6T898020	L.H. Cable Adjusting Bolt Unit	A	
6	Y6T842000	Clamp Bolt (M5 x 13.5)		
* 7	Y6UV98090	Bolt & Nut Unit for SM-SL98-B	A	

A: Same parts.
B: Parts are usable, but differ in materials, appearance, finish, size, etc.
Absence of mark indicates non-interchangeability.

Mar.-2013-3310A
© Shimano Inc. A

Specifications are subject to change without notice.

SHIMANO