



Bezeichnung	L <sub>1</sub> (mm)	L <sub>2</sub> (mm)	L <sub>3</sub> (mm)	B (mm)	D <sub>1</sub> (mm)	D <sub>2</sub> (mm)	Übertragbares Drehmoment Mt (Nm)	Axialkraft F ax. (kN)	Flächenpressung Welle P <sub>w</sub> (N/mm <sup>2</sup> )	Flächenpressung Nabe P <sub>N</sub> (N/mm <sup>2</sup> )	Schrauben - Anzahl	Schrauben - Bezeichnung	Schrauben - Anzugsmoment Ms (Nm)	Gewicht (kg)	
<b>CE02</b>															
CE02 08	12	21	24	28	28	32	39	10	299	159	4	M4x10	5,2	0,16	
CE02 09	14	23	27	31	28	32	44	10	227	128	4	M4x12	5,2	0,16	
CE02 10	14	23	27	31	28	32	49	10	205	128	4	M4x12	5,2	0,17	
CE02 11	14	23	27	31	30	34	53	10	186	114	4	M4x12	5,2	0,17	
CE02 12	14	23	27	31	30	34	58	10	171	114	4	M4x12	5,2	0,18	
CE02 14	14	23	27	31	35	39	68	10	146	89	4	M4x12	5,2	0,20	
CE02 15	16	29	36	42	40	45	120	16	196	123	4	M6x18	17	0,21	
CE02 16	16	29	36	42	40	45	128	16	184	123	4	M6x18	17	0,23	
CE02 18	18	31	38	44	42	47	191	21	194	134	4	M6x18	17	0,27	
CE02 19	18	31	38	44	43	48	202	21	183	129	4	M6x18	17	0,29	
CE02 20	18	31	38	44	44	49	213	21	174	124	4	M6x18	17	0,30	
CE02 22	25	38	45	51	48	54	234	21	114	78	4	M6x18	17	0,38	
CE02 24	25	38	45	51	50	56	255	21	105	74	4	M6x18	17	0,41	
CE02 25	25	38	45	51	50	56	266	21	100	74	4	M6x18	17	0,45	
CE02 28	25	38	45	51	55	61	373	27	112	81	5	M6x18	17	0,47	
CE02 30	25	38	45	51	57	63	480	32	126	92	6	M6x18	17	0,48	
CE02 32	30	43	50	56	59	65	511	32	98	73	6	M6x18	17	0,51	
CE02 35	30	43	50	56	63	69	747	43	120	89	8	M6x18	17	0,63	
CE02 38	30	43	50	56	66	72	811	43	110	84	8	M6x18	17	0,67	
CE02 40	32	45	52	58	69	75	959	48	110	83	9	M6x18	17	0,73	
CE02 42	32	45	52	58	71	77	1007	48	105	80	9	M6x18	17	0,78	
CE02 45	40	56	64	72	79	85	1781	79	130	99	8	M8x22	42	1,23	
CE02 48	40	56	64	72	82	88	1900	79	122	94	8	M8x22	42	1,24	
CE02 50	50	66	74	82	85	92	2473	99	117	90	10	M8x22	42	1,40	
CE02 55	50	66	74	82	91	98	2721	99	106	82	10	M8x22	42	1,70	
CE02 60	50	66	74	82	97	104	2968	99	97	76	10	M8x22	42	1,76	
CE02 65	50	66	74	82	104	111	3215	99	90	69	10	M8x22	42	2,21	
CE02 70	60	80	91	101	115	122	4430	127	89	69	8	M10x25	84	3,05	
CE02 75	60	80	91	101	119	126	5338	142	93	74	9	M10x25	84	3,32	
CE02 80	65	85	96	106	124	131	7595	190	108	86	12	M10x25	84	3,50	
CE02 85	65	85	96	106	130	137	8069	190	101	81	12	M10x25	84	3,60	
CE02 90	65	85	96	106	136	143	9968	222	112	90	14	M10x25	84	3,90	
CE02 95	65	85	96	106	144	153	10522	222	106	84	14	M10x25	84	4,40	
CE02 100	65	89	102	114	153	162	13651	273	124	99	12	M12x30	145	4,60	
CE02 110	70	94	107	119	168	177	15016	273	105	82	12	M12x30	145	8,70	
CE02 120	90	114	127	139	185	195	21844	364	99	77	16	M12x30	145	10,70	
CE02 130	90	114	127	139	195	205	23664	364	92	72	16	M12x30	145	11,30	
CE02 140	90	114	127	139	205	215	25485	364	85	68	16	M12x30	145	11,90	
CE02 150	90	114	127	139	215	225	27305	364	80	64	16	M12x30	145	12,50	